






Keep on Partnering: OR-FACE Meets Oregon Trucking Associations

Barb Epstien, MPH, CIH, FAIHA WestON 2018 Denver, CO





Why Trucking?

~70% freight by truck

Inherent hazards

2X obesity



10+ Years Partnering







Safety and Health Improvement for Truck Drivers

Weight & health promotion program

Sleep /
eating /
exercise
elements

Improve driver safety, health, well-being

NHLBI R01 #HL105495









Behavioral sleep intervention (adapted from SHIFT)

Cab engineering controls to alter whole body vibration


*Improve sleep

*Reduce fatigue

*Total Worker Health®




OTA Safety Mgt Council






OREGON TRANSPORTATION FATALITY TRENDS: 2003-2016

2003-2016 Oregon Transportation Fatalities











...by season






...by age






...by time of incident





...by day of the week





2016 Oregon Trucking Fatalities

Overturned truck truck

- Rear-end
- Head-on
- Struck by

Example 1 Commercial freight

- Logging
- Gasoline

Handle Interstate

- US highway
- Other / unknown





OREGON FATALITY ASSESSMENT AND CONTROL EVALUATION

4. Sept. Committed respectively and former properties. NEWSTRAFFING SOMEWHATTER MODIFIES AND

Oragon Institute of Occupational Faulth Sciences



Fatality Investigation Report

OR 2014-1-1

Driver killed when ejected from logging truck

FACE INVESTIGATIONS

assuld hade truck detected recognize amoufs delvine conditions and to aration when conditions are upule


Applier truck fleel owners that require operation under the candidara should incodd front log house in trucks and casure that lights are working and windshields and cat whateverage clean.

- Defects should use wat belts when operating a logging track and unphysics should culorex cubiling sens bell use policies
- Defeare should clean their windshields as after as needed and conduct regular. vehicle impections to course first brakes are working correctly.

Semi-truck Owner-Operator Crushed by 7.6-ton Steel Coil While Securing Load to Flatbed Trailer



Tanker Truck Involved in Deadly Crash on Interstate



Truck Driver Crushed between Semi-trailer and Loading Dock

